
Wetterstation Plus für KNX - Release Notes

Artikel-Nr. 2074 00 ab Indexstand I07

Firmware-Version: 3.0

Datum: 23.05.2025

- Fehler innerhalb der Sonnenstands-Ermittlung
Durch Unterbrechungen des GPS-Empfangs, konnte ein Fehler innerhalb der Sonnenstands-Ermittlung auftreten, der dazu führen konnte, dass es zu einem kurzen Auf-/Ab-Fahren des Behanges kam.
- Indexstandänderung aufgrund Bauteilabkündigung
Aufgrund einer Bauteilabkündigung, wird es zukünftig den Hardwarestand **I07** geben. Dieser erfordert die Applikationsversion 3.0, die ebenfalls den oben beschriebenen Bugfix enthält.

Weather station Plus for KNX - Release Notes

Order no. 2074 00 from index level I07

Firmware version: 3.0

Date: 23.05.2025

- Error in the sun position determination
Due to interruptions in GPS reception, an error could occur in the sun position determination, which could result that the blinds briefly moving up and down.
- Index status change due to component discontinuation
Due to a component discontinuation, the hardware version **I07** will be available in the future. This requires application version 3.0, which also contains the bug fix described above.